



MARYLAND DEPARTMENT OF THE ENVIRONMENT

LAND and MATERIALS ADMINISTRATION

SOLID WASTE PROGRAM

1800 Washington Boulevard Suite 605

Baltimore Maryland 21230-1719

(410) 537-3315 • 1-800-633-6101 • [https:// mde. maryland. gov](https://mde.maryland.gov)

Inspector(s): <u>Michael Brown</u>	AI #	<u>179649</u>
Type(s) of Inspection: <u>SWP – RD Report of Observations</u>	Date:	<u>1/4/2024</u>
Site/Facility Name: <u>CSX Transportation Inc – Baltimore Ave crossing in Hyattsville</u>	Time In:	<u>11:05am</u>
Location: <u>375ft NE of Baltimore Ave and Emerson St, Hyattsville, PG Co, MD 20783</u>	Time Out:	<u>12:30pm</u>

Permit / Approval Numbers: N/A

Site Status: Inactive

Info Collected: Visual observation, and a selection of photos shown on pages below.

Weather: 37°F Overcast No Precipitation Moderate Breeze

Field Conditions: Dry

Findings: This was an unannounced site visit to monitor the cleanup progress since 12/11/2023 visit. The site is inactive today. Prior to this inspection, CSX indicated that HEPACO was on site on 12/21/23 working on clean up in areas discussed on 12/11/23 meeting. An inspection of areas along the access road at the southern perimeter of the site shows no visible pellets, with inspection areas of previous accumulation. Southeastern, downgradient areas along the tracks past the end of the access road are still showing no signs of pellet migration. There are a few areas with pellets present in the large aggregate (within ~5 feet of the track to the south) along the ~600ft portion of track between Baltimore Ave and the end of the access road (see photos).

Summary:

1. Site was inactive at this time
2. Pellets are still present within track aggregate
3. Pellets along SE perimeter areas have been removed
4. Based on visual observations, the clean-up is considered completed, and no further action is required.

Operating without a permit or license or in violation of a permit or law may result in the assessment of civil or administrative penalties. Each day a violation occurs is a separate violation. Please be advised that this inspection report is a public record and as such, is accessible to the public.

Inspector: Michael Brown *Michael Brown*
Michael.brown7@maryland.gov

Received by: _____
Signature/Date

Report provided to:

- Email
- Regular Mail
- Certified Mail
- Hand Delivered

Contacts at: CSX, City of Hyattsville, and PG County

Print Name

Selection of photos taken 1/5/2023



CSX equipment on site



Pellets observed within aggregate bordering track



SW view of site



Close up of pellets along track in aggregate



No visible pellets in previously collected area



SE boarder pellets removed